
Analysis of the Crump Theatre







Our Charge.....
What is the role of The Crump?

- 8 Previous Studies
- Columbus Area
 Performing Arts Needs

Feasibility Can The Crump be:

- Study Redeveloped?
 - Re-purposed?
 - Renovated?

Study Contents

- Background
- Potential Role of The Crump
 - Area Demographics
 - Other Facilities
 - Comparable Markets
 - Missing from Columbus
 - Modern Audience Expectations
 - Can Crump Meet the Needs?



- Life Safety
- Structural Evaluation
- Building Services





- Theatre Site and Options
 - Existing Crump and Site
 - 2001 Plan
 - Renovated Crump
 - New Crump
 - Alternate Site
 - YES Cinema

- Visible Arts
- Center of Activity
- More Opportunities
- Goals Enhanced Community Assets
 - Multi-functional day and night
 - Improved Arts Education
 - Keep \$\$ Here!

- Diverse
- Volunteer Drivenbut with limited resources
- Columbus
- Limited by Facilities
- Arts are Lacking Collaboration

- Diverse
- Sufficiently populated
- Interested in the Arts
 - Lacking Collaboration

Bartholomew County is....

Other Facilities

School:

- East High School
- North High School
- Central Middle School

Other:

- The Commons
- Mill Race Center
- Mill Race Amphitheatre
- YES Cinema
- Harlequin Theatre
- Alternative Spaces
 - (Churches, Libraries, etc)

- Ames, Iowa
- Cheyenne, Wyoming
- Dubuque, Iowa
- Peer Jefferson City, Missouri
- Cities Kokomo, Indiana

Milken Institute Best-Performing Small Cities Index

No community performing arts facility

- No community civic theatre
- No community children's theatre
- No touring entertainment
- No conference/exhibit/display



Large Room

- Conference
- Exhibit
- Display


Intimate Arts Facility

- Local Users
- Columbus 350-450 seats

Needs• Performing Arts Center

- Professional Tours
- Larger Local Users
- 1200-1500 seats

Can The Crump be re-purposed?



Current
Status
of the
Crump

5 major renovations numerous minor renovations

- Life Safety Code Compliance
- Structural Integrity
- Audience Support
 - lobby
 - restrooms
 - disabled users accessibility


Current Status of the Crump

Production Support

- stage size
- load-in
- dressing rooms

Acoustics

- **Building Services**
- water, sewer, electrical




Public Seating Code Compliance










1939-40 renovation









disrepair disrepair

fall hazard – 28"drop improperly mounted seats

fall hazard – 28"drop







Stage Venting

building section originally by Louis Joyner, Architect

Reverberation and Acoustics







Building Section optimum geometry for acoustics

Structural Integrity

- Stage Roof ('flyhouse')
 - stage size
 - load-in
 - dressing rooms
- Stage Floor
 - Doesn't support current show loads
- Mechanical Room Structure
 - Unsafe due to rusting
 - Seismic Code
 - Applicable to southern Indiana

Scenario Development





- No community civic theatre
 - No community children's theatre
- No touring entertainment
- No conference/exhibit/display




Footprint: 9,267 sf

Lot: 11,359 sf



- Seats 632
- No accessible restrooms
- No backstage restrooms
- Basement dressing rooms
- No production support
 - light, sound, rigging
- No load-in dock



Renovate Crump

300-450 seats

YES Cinema


320 fixed seats, flat floor

YES Cinema

- 400 fixed seats, raked floor
- New venue 1000 seats
- New venue 1200 seats



Expansion




Crump Theatre Additions 300-450 seats

Pros


retains Crump presence
expanded lobby
accessible public restrooms
accessible dressing rooms
greater stage depth
improved show load-in
improved acoustics


Cons

stage size limits show potential additional costs









New Performing Arts Center 1000 seats


third street


Pros

larger seat count
larger stage
improved load-in
reuse of marquee & materials

Cons

demolition of the Crump
needs property acquistion
inadequate seat count
stage size limited
no accessible restrooms
no main level dressing rooms
'cramped' design








New Theatre 1200 seats


Pros


near optimum seat count comfortable lobby accessible public restrooms on all floors greater show capability patron drop-off on Franklin multiple entries reuse of marquee and materials

Cons

greatest costs for site
needs property acquisition
honors Crump's vision, but
not the building
'cramped' design
dressing and storage rooms
in basement







YES Cinema Renovations 300 seats

Pros

maintains one existing cinema maintains existing toilets multipurpose flexible space near hotel and restaurant available to IUCAD

Cons

limited performance capability limited seating






Construction Costs






Operational Costs



SEARS

Game Changer...




Pros

retains Crump presence expanded lobby accessible public restrooms accessible dressing rooms greater stage depth improved show load-in improved acoustics

Cons


lobby still too small stage size limits show potential additional costs



Columbus Indiana Theatre/Convention Center Single Block Option

What of The Crump?

free to evolve.....




'Evolved' Crump


Pros

retains Crump presence
expanded lobby
accessible public restrooms
accessible dressing rooms
no work on existing stage
Small thrust stage
Improved acoustics
minimum costs

Cons

very limited performance capability minimum production support






2nd Floor




New



'evolved' Crump

building section originally by Louis Joyner, Architect



- 1. No matter what choices are made, Columbus needs better communication about the arts opportunities and facilities.
 - Someone who can promote and speak for all of the venues, providing information for potential users that includes fees, availability, services and local information.
 - A comprehensive arts web site.
 - All facilities should be listed in the Pollstar Venue
 Directory with contact information.

- 2. If the Crump Theatre must serve one of the two performing arts needs that require a proscenium stage
 - Then it must be brought into compliance with current code - IBC 2010
 - We understand the desire to preserve the building's history
 - We also know that to accomplish this is more expensive in a historic structure than in new construction

- Consider the Sears site:
 combine the performing arts needs with
 other community goals.
 - IU-CAD
 - Conference/meeting/exhibit/display
 - Performance Space for Local Groups that could be also be used for Meetings, Reception, Display, etc.
 - Professional Touring Show Performance Venue

4. Consider a renovated Crump:

- Provides the need of a 300-450 seat multipurpose venue.
- It reactivates its use
- It saves The Crump's best architectural character


Crump Theatre Additions 300-450 seats

Pros

retains Crump presence
expanded lobby
accessible public restrooms
accessible dressing rooms
greater stage depth
improved show load-in
improved acoustics

Cons

stage size limits show potential additional costs



5. Consider an 'evolved' Crump:

- If low initial costs are a priority, this provides new and different uses.
- It reactivates its use
- It saves The Crump's best architectural character


'Evolved' Crump

Pros

retains Crump presence
expanded lobby
accessible public restrooms
accessible dressing rooms
no work on existing stage
Small thrust stage
Improved acoustics
minimum costs

Cons

very limited performance capability minimum production support





New

Questions?





